

D&D Facility Characterization Interview Checklist

ID No.: <u>K771N</u>
Date: 10/09/00

Page 1 of 2

Check List for - Title: D&D Facility Characterization -

CRITERIA:

Λ D&D Characterization Protocol, RFETS MAN-077-DDCP, Rev. 0

Λ Facility Disposition Program Manual, RFETS MAN-076-FDPM

Λ RFETS Radiological Safety Practices, January 12, 1998

Facility Name & Type (1, 2, or 3) Building K771N, Type 1 Facility, Modular Hot Food Facility
Personnel Interviewed (Name & Title/Function) Don L. Cox, Mechanical Engineer V, D&D Closure
Y/N
Does a current WSRIC exist for the facility? N
If so, are there exceptions to the WSRIC as written?
COMMENTS (incl. WSRIC contacts)
WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83.
Are rad surveys available that indicate current status of the facility? N
Are historical rad surveys available that indicate historical status, or evolution, of the facility?
COMMENT N* According to Sarah J. Roberts, X3008, ARCDA, T771Q, any
Historical data, which is probably at the Federal Center, would not be adequate for unrestricted release (i.e. Pre-
Demolition Survey or Property Release Evaluation). New monitor surveys would have to be taken.
Is an HRR available for the facility?
Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further
Characterize the facility relative to chemical &/or radiological contamination? N*
Are engineering drawings (esp. "as-builts") available?
 Engineering as-built drawings are not available, but facility room drawing/sketches are available.
Are any non-conformances or issues with the facility status currently being tracked in PATS?
If so, what are the issues (note in Comments, below)?
COMMENTS N* The K771N Trailer sits on IHSS/PAC 700-150.2 and/soils, as per, Nick Demos, ER
Characterization/HRR Manager, X4605, Therefore, the K771N land/soils has CERCLA concerns.
Engineering drawings, as-builts, do not exist for the K771N facility, but a Facility Planning sketch does
exist. This facility should not contain any lead-based paints because the facility is only approximately 1
year old.
Have any types of chemical characterization, incl. Asbestos, been performed recently?
If so, what types of characterization were performed (note in Comments, below)?
COMMENTS N* No asbestos characterization data exists for Building K771N Hot Food Facility
according to Bret Clausen, X, Building 130, Room C-252. The asbestos data reports are located in
Cubicle 273, of Building 130 and the reports are under the control of Bret Clausen with Rae Eklund
As backup contact for the asbestos reports. K771N is new enough (1 year old) that it probably does not
contain any asbestos.
$\sim \sim $
Interviewed by: I. R. Sheets / 10/09/00
Interviewed by. 3.11. Sheets
Print Name Signature Interview Date

39 1/2



ADMIN RECCRD



D&D Facility Characterization Interview Checklist

ID No.: <u>K771N</u>
Date: 10/09/00

Page 2 of 2

What timeframe did the interviewee work in the facility? N/A. K771N is a prefabricated Hot Food Facility.

Has the building configuration changed since you worked in the building? If so, in what way?

What types of equipment were in the building during the interviewee's time there? N/A, the facility was prefabricated as a Hot Food Facility.

Where was the equipment located? (specific rooms/areas) Throughout the small dedicated prefabricated Hot Food Facility.

Were any radioactive materials or metals handled in the building? If so, what types? No, none

Which equipment handled radioactive material? N/A

No, the facility is still a prefabricated Hot Food Facility.

Were any chemicals handled in the building? If so, what types? N/A

Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No, none.

Were these spills/releases cleaned-up? How were they cleaned-up? N/A

Where did these spills/releases occur? N/A

Interviewed by: J. R. Sheets / 10/09/00

Print Name Signature Interview Date

W2/2